

|                                                                                                                                                                                                                                              |                                                                                                                                                                           |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>BST Eltromat France SARL</b><br>Impasse de la Noisette - CE402<br>F-91374 Verrières le Buisson<br>Tél.: +33 1 69 20 07 41<br>Email: bstfrance@bst.group<br>Web: <a href="https://www.bst.elexis.group/">https://www.bst.elexis.group/</a> | <b>Amcor (Sarrebouurg)</b><br>231254<br>M. Thierry Richard<br>48 rue de Sarreguemines<br>57400<br>Sarrebouurg<br>France<br>+33 3 87 24 53 43<br>thierry.richard@amcor.com |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                                     |                                |
|-------------------------------------|--------------------------------|
| Preventive reference number         | PMREPORT-246_PM851_2025-03-27  |
| Contract number / Numéro de contrat | Please fill system information |
| Contract date:                      |                                |
| Machine customer name:              | 253                            |
| Assign to:                          | RelR                           |
| Material:                           | VIDEO_IPQ_Check_eco            |
| Type:                               | iPQ Center Eco                 |
| SN:WA:                              | ASO056935_WA20714              |
| Installation date of material:      | 2019/06/05                     |

#### TECHNICAL DATAS

|                                       |                                 |
|---------------------------------------|---------------------------------|
| PC MODEL                              | Bste01                          |
| PC NAME                               | 20714ipqCenter 1-2              |
| ADDITIONAL CAMERA INFO                | iPQ Center Eco                  |
| OPERATION SYSTEM                      | WINDOWS 10 ENTERPRISE           |
| MEMORY RAM                            | 32Go                            |
| FREE SPACE ON C                       | 52.9Go/ E:41.7Go                |
| FREE SPACE ON D                       | 83Go / F: 1.81Tb                |
| TEAMVIEWER ID                         | 293 992 682                     |
| IP ADDRESS EXTERN FOR INTERNET        |                                 |
| ORIGINAL VERSION                      | 2.14.1                          |
| UPG OR DNG VERSION DURING MAINTENANCE | No software upgrade recommended |

|                |                  |
|----------------|------------------|
| Start time PM: | 26/03/2025 09:15 |
| End time PM:   | 26/03/2025 11:30 |

|                                        |   | COMMENTS    |                               |   | COMMENTS                                         |
|----------------------------------------|---|-------------|-------------------------------|---|--------------------------------------------------|
| Touchmonitorcalibration                | ✓ |             | Ipqchecksynchronization       | ✓ |                                                  |
| Pcscreenresolutiontouch                |   | 1920X1080   | Ipqencoderwheelfixing         | ✓ |                                                  |
| Pcscreenresolutionview                 |   |             | Ipqencoderwheelstatus         | ✓ |                                                  |
| Hardwareconditionscrews                | ✓ |             | Ipqencoderwheelrunningonweb   | ✓ |                                                  |
| Hardwareconditioncables                | ✓ |             | Alarmstatusindicator          | ✓ |                                                  |
| Hardwareconditionconnectors            | ✓ |             | Upsbatteryexchanged           | ⏸ |                                                  |
| Digitalcheckfan                        | ✓ |             | Upsdatebatteryexchanged       |   | UPS builder recommend to exchange every 4 years. |
| Digitalreplacefilter                   | ✓ |             | Installation date:            |   | 2019-06-05                                       |
| Linecameracleanmirror                  | ✓ |             | Upscommunicationchecking      | ✓ |                                                  |
| Led checking+reflector checking+dome   | ✓ | Dome Craqué | Softwareupdate                | ⏸ |                                                  |
| Linecameramechanicalcheck              | ✓ |             | Version upgraded              |   |                                                  |
| Linecamerabacklightmechanicalcheckjigs | ✓ |             | Softwareipqtcu                |   | 1.9.1                                            |
| Cameramechanicalalignementtoprint      | ✓ |             | Softwareipqili                |   | 1.4.3                                            |
| Camerawhitecalibration                 | ✓ |             | Softwareworkflowcommunication | ✓ |                                                  |
|                                        |   |             | Softwareremote                | ✓ |                                                  |
|                                        |   |             | Operatorinstructions          | ⏸ |                                                  |
|                                        |   |             | Backupscreenshots             | ✓ |                                                  |
|                                        |   |             | Backupimage                   | ✓ |                                                  |
|                                        |   |             | Backupsoftware                | ✓ |                                                  |

- ✓: Checked, nothing to report / Vérifié, RAS  
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires  
 ⏸: Not actif / Non Actif

#### Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:


Date :

BST eltromat FRANCE signature:

Name:

Date :

  
28/03/2025 14:08

  
31/03/2025 11:50