

On Customer Site

Visit Report

Reference :

Commande BSTe France : CM1803014		Commande BSTe Int. : PM284	
Customer :	Imprimerie Billet	System :	TubeScan DS 430 HR2
Customer Contact :	M. Jérôme Nivart	SN :	34.326
Customer Order number :		Machine Nickname :	SIRIUS II

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	15 /12/2021					
Travel To	0					
Start Time	10h30					
Lunch Time	0					
End Time	11h30					
Travel From	0					

Details	Maintenance preventive et Acronis système .
---------	---

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for NYQUIST Systems

Available supporting documents :

- Maintenance instruction for Digital Strobe & EagleView systems
- Check list for maintenance

Customer name and place : [Imprimerie Billet / 6 rue de Romery – 51480 - Damery](#)

Contact person at customer : [M. Jérôme Nivart \(Responsable Qualité](#)

Customer Mail & Mobile/Landline : Jerome.nivart@imprimerie-billet.fr r/ +33 326584011

System Type : [DS 430 HR2](#)

SN : [34.326](#)

Machine Manufacturer/Model/Nickname : [SMAG / SIRIUS / SIRIUS II](#)

Date : [15/12/2021](#)

Name : [Richard Relin](#)


Comments :

Signatures :



Richard Relin 2021-12-16T09:56:54+01:00

BST eltromat FSE



Jerome Nivart 2021-12-15T15:28:03+01:00

Customer

On Customer Site

Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

1. Cleaning the optical parts :

OK/NOK/NA

- Mirror cleaned with ZEISS lens wipes. ☒ ☐ ☐
- Camera lens cleaned with ZEISS lens wipes. ☒ ☐ ☐
- Reflectors cleaned with soft cloth using iso propanol or alcohol. ☒ ☐ ☐
- Backing Bar cleaned with soft using iso propanol or alcohol. ☒ ☐ ☐
- Optionally acryl insert of backing bar replaced. ☐ ☒ ☐

2. Check functioning of the LEDs :

OK/NOK/NA

- LEDs checked. ☒ ☐ ☐
- Brightness and uniformity of the image checked. ☒ ☐ ☐

3. Replacement of the encoder wheel :

OK/NOK/NA

- Encoder wheel replaced and tightened ☐ ☒ ☐
- Spring replaced (if necessary) and spring force checked (ca. 1kg/10N) ☐ ☒ ☐

4. Software update :

OK/NOK/NA

- Software Update (if necessary). ☐ ☒ ☐

Old SW version : [6.2.25.75](#)

New SW version :

On Customer Site

5. Final check of the running system :

OK/NOK/NA

- | | |
|--|---|
| - Stability of live image checked (without reference image). | ☒ ☐ ☐ |
| - Stripe alignment checked (Normal and reflective mode). | ☒ ☐ ☐ |
| - Registration checked. | ☒ ☐ ☐ |
| - Maximum speed checked. | ☒ ☐ ☐ |
| - Stable location of the EagleView camera checked. | ☐ ☐ ☒ |
| - Hard drive capacity checked. | ☒ ☐ ☐ |
| - Backup created and saved locally and/or on USB stick. | ☒ ☐ ☐ |

6. Backup :

OK/NOK/NA

- | | |
|--------------------------------------|---|
| - NYCAMConfig folder | ☒ ☐ ☐ |
| - NYCAMProg folder | ☒ ☐ ☐ |
| - WindowsImageBackup and/or Image | ☒ ☐ ☐ |
| - Application / Computer Screenshots | ☒ ☐ ☐ |

Parts replaced during Preventive Maintenance :

- | | |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

Parts suggested to replace during the next Maintenance :

- | | |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

Part need to be replaced as soon as possible :

- | | |
|-----|-----|
| 1 - | 4 - |
| 2 - | 5 - |

On Customer Site

Technical datas

Computer name : **Tubescanpc**

Total Physical Memory : **8 GB**

Free Space in C Drive (System) : **390 GB**

OS : Windows 7 Pro

Screen Resolution Touch : **1024X768**

Screen Resolution Full View : **1680X1050**

Computer Model : Optiplex 9020

Date : **2015**

Remote Maintenance (Teamviewer)

IP address : **DHCP**

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : 875 864 641 / v12

On Customer Site

Notes
